IDEA 0136-69 Copy 7 of /4

22 April 1969

MEMORANDUM FOR: Director of Special Activities

SUBJECT

: Headquarters Tactical Evaluation Team Report on SCOPE SAINT II, April 1969

25X1

- l. The Headquarters Tactical Evaluation Team (Colonel William E. Shelton, accomplished an evaluation of the Headquarters ability to plan, direct and control the deployment of one U-2R from Edwards AFB California, to and to fly one simulated operational mission.
- 2. The Headquarters satisfactorily demonstrated its capability to deploy the subject aircraft and to plan, direct and fly a simulated operational mission. The actions planned and taken prior to the U-2R/forklift incident were considered adequate and sufficiently demonstrated operational staff capability even though the evaluation was terminated after the incident.
 - 3. There were no major or limitating factors.
 - 4. The following team observations/comments are submitted:
 - a. The team considered all pre-mission coordination and planning to be much improved over the last SCOPE SAINT deployment. Additionally, appropriate personnel at AFIGOS and Loring Air Force Base should be complimented for their outstanding support.

25X1

b. The initial operations order required clarification
with regard to the duties and responsibilities of
Recommend that future plans spell out their
precise responsibilities with regard to command control inputs
or message handling.

25X1

25X1

25X1

GROUP I
Excluded from automatic
awagrading and declassification

25X1

Approved For Release 2003/12/11 : CIA-RDP75B00285R000300070052-5

IDEA 0136-69 Page 2

- c. Headquarters directives do not provide for support airlift arrival and departure messages. Recommend that Reports Control Manual be amended accordingly.
- go-no-go terminal weather forecast criteria required last minute change when forecast weather This age-old problem is caused by the disparity between generally pessimistic 24 hours plus forecasts and conservative use of higher published let down minima. For planning purposes recommend that future deployments be based upon published GCA or ILS weather minima provided sufficient fuel is available to proceed to a suitable alternate. As mission count down progresses consideration should include: equipment reliability; pilot proficiency and fatigue if any; urgency of mission; and the political pros and cons of diverting aircraft to an alternate.
- At least one SCOPE SAINT II Annex (Annex F) message were released by other than the and one IDEALIST Division. Recommend that all Hqs staffs who generate operations Annexes or traffic prepare and authenticate messages for final release by the IDEALIST Division.
- f. An attempt was made to employ long distance telephone communications with the deployed detachment during a period that all deployed personnel should have been resting. Normal project communications are adequate for most situations. The use of long distance telephone, HF, or other back up communications methods must be restricted to unusual emergency conditions, or when normal communications are inoperative.
- g. Future use of the buddy-tactics should be carefully evaluated especially when the planned mission involves an en route stop, take off and rendezvous. The Team's opinion is that mission success rests too heavily upon the guaranteed take off of an en route deployed support aircraft. Last minute support aircraft problems or below take off weather minima could well turn mission into chaos should it become necessary to abort the U-2 for one reason or another. Additionally,

25X1

25X1

25X1

25X1

25X1

Approved For Release 2003/12/11 : CIA-RDP75B00285R000300070052-5

IDEA 0136-69 Page 3

it is believed that under most conditions it would be advantageous to deploy the support aircraft ahead of the U-2 to the maximum extent possible. In the long run the deployed personnel and equipment will be better prepared to receive and handle the aircraft upon its arrival and immediately commence follow-on mission generation. This would also enable the deployed commander and his key staff to better supervise and manage resources.

h. The Headquarters staff should become and remain more knowledgeable of the unit deployment plans. This is particularly true on those items such as cameras, weather packages, processing equipment, etc., as political or cover conditions might dictate various U-2/support aircraft loading options. The next time this plan is exercised both the Headquarters and the unit may be involved in a crisis situation wherein less than 24 hours is available for coordination.

i. A requirement exists for the Security and Communi-

	cations staffs to provide appropriate addressing instructions
•	for message traffic when dealing with
	25X1
	j. The sequence of events and the mechanics of obtaining the necessary final approvals of the U.S. Intelligence Community for the cover/contingency plan is
	cumbersome and time consuming. Recommend Cover Staff/OSA review these procedures with the intention of providing a mechanism for obtaining more expeditious final approvals.
	25X1
	WILLIAM E./SHELTON
	Colonel, USAF
	Deputy for Operations, OSA
APPRO	OVED:

25X1

25X1

25X1

Director of Special Activities 24 6 9

25X1

CROUP)

Excluded trans a stemator

dawngrading and declassification

Approved For Release 2003/12/11: CIA-RDP75B00285R000300070052-5

IDEA 0136-69 Page 4

OSA/D/OPS/Shelton:ren(22 April 1969)

Distribution:

- 1 D/SA
- 2 D/M
- 3 D/O
- 4 R&D
- 5 COMPT
- 6 SS/OSA
- 7 AMS/OSA
- 8 INTEL/O
- 9 IDEA/O
- 10 WX/O
- 11 COMMO/O
- 12 CC/O
- 13 SAS/O
- 14 RB/OSA

25X1

ากกั

CLASSIFICATION

SECRET

IDEA 0136-69 Copy 7 of 14

THIS DOCUMENT REQUIRES SPECIAL HANDLING

HANDLING PROCEDURES

THIS DOCUMENT CONTAINS INFORMATION REGARDING A HIGHLY CLASSIFIED ACTIVITY. PERMISSION TO TRANSFER CUSTODY, OR PERMIT ACCESS TO THIS DOCUMENT MUST BE OBTAINED FROM THE ORIGINATOR. HAND CARRY PROCEDURES WILL BE APPLIED TO ANY INTER-OFFICE OR INTRA-AGENCY MOVEMENT OF THIS DOCUMENT.

Distribution for AMA/OSA
25 APR 1969
DATE
JEE
DFF
BEB 3803

IDEALIST

25X1

CLASSIFICATION

SECRET

Approved For Release 2003/12/11 : CIA PDD75R00285R000200070052 5